



APPLICATIONS NOTICE

temperzone limited
Auckland, NEW ZEALAND.
Phone 0-9-279 5250, Fax 0-9-275 5637
Email sales@temperzone.co.nz

temperzone australia Pty Ltd
Sydney, AUSTRALIA.
Phone (02) 8822 5700, Fax (02) 8822 5711
Email sales@temperzone.com.au

Form NS 006

TO: ALL TRADE CUSTOMERS
H.O., REG'L & AUST. MANAGERS

ISSUE NO. : 03/05

DATE : 1 June 2005
FROM : T KING/K EDWARDS

SUBJECT: ICAR TYPE PO PLASTIC CAPACITOR FAILURES


UNITS: ALL UNITS CONTAINING SINGLE PHASE COMPRESSORS
AND/OR FAN MOTORS

From 1999 to mid 2004 we supplied our units with this type of capacitor.

A very small percentage of these have failed after some time in the field.

This defect is not one of temperzone's manufacture. It has come to our notice not only through the isolated instances with our own product, but to a greater extent through the combined experiences of other Australasian manufacturers who have also used this type of capacitor.

Manufacturer



Type "PO"

To put the defect in context, we supply over 50,000 capacitors in our units each year and we estimate that to date failures are approximately 0.1% of this figure.

Nevertheless, we are prepared to sponsor the replacement of all of these capacitors installed in our units. Since the Italian manufacturer ICAR has declined responsibility, **temperzone will supply replacement capacitors free of charge.**

Since we do not have records of the on-sale and eventual location of our products, we have to rely upon you to identify and replace these capacitors when you do the 6 monthly maintenance services as required per the Installation and Maintenance brochures supplied with our product. temperzone will pay reasonable labour costs incurred by you for the replacement of capacitors during a scheduled service.

However, should you be called upon to rectify any capacitors that have failed, please replace all other capacitors of this type that are at the same location. temperzone will meet the reasonable labour costs incurred by you in this situation.

Through these cost-efficient methods of replacing capacitors during scheduled services and by replacing many where one has failed, we will be able to undertake replacement of all capacitors within a reasonable time frame.

If you are involved in the regular servicing of our units, please order (free of charge) a minimal starting quantity of replacement capacitors, stating the quantity and ratings required.

After replacement, please return a completed "Capacitor Replacement Requisition form as attached. You may then order more free replacement capacitors, provided you have supplied us with the quantities, ratings and location of earlier replacements per the previously completed Capacitor Replacement Requisition Form.

CAPACITOR REPLACEMENT REQUISITION
 (refer Application Note 03/05 for full details)



38 Tidal Road, Mangere, Auckland, NZ
 Private Bag 93303, Otahuhu, Auckland, NZ
 Phone: +64-9-2795250 Fax: +64-9-2755637
 Email: sales@temperzone.co.nz

Client to complete:
 (Please fill in as much info as possible)

Date: _____

Client Name: _____

Job Name/Location: _____

Unit Model	Serial No	Capacitors	Quantity
		mfd	
		mfd	
		mfd	
		mfd	
		mfd	
		mfd	
		mfd	
		mfd	
		mfd	
		mfd	
		mfd	

Temperzone to complete:

Client No: _____

Processed by: _____

Date Processed: _____

Part No.	Comments

for client:.....
 (signature required)

No Charge Invoice No.:
 (To "Capacitor Replacement" file on completion)